

## PHOTO GALLERY



**RAIL MAINTENANCE VAN ( RMV )**



**KHADEM SOIL CUTTING**




**RAJAPUR SOUTH FRACTURED ROCK CUTTING**



**CHINCHAVALI FRACTURED ROCK CUTTING**



**GRASS PLANTATION ON CUTTING SLOPE**



Loose boulder  
trapped in  
boulder net

**STEEL BOULDER NET**



Rock bolting

**ROCK BOLTING IN KARBUDE TUNNEL**



Shotcreting of tunnels

**SHOTCRETING IN KARWAR TUNNEL**



Gabion wall

### GABION WALL IN CUTTING

“Last Updated – August 2017”